
03500.015636.





IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)) : Examiner: C. Quiett) : Group Art Unit: 2612)	
NORIYUKI KAIFU, et al.	;		
Appl. No.: 09/916,264	;		
Filed: July 30, 2001)		
For: IMAGE SENSING APPARATUS INCLUDING AN IMAGE SENSING UNIT HAVING A NON-DESTRUCTIVE READ FUNCTION)		
U.S. Patent No.: 6,947,084 B2	;		
Issued: September 20, 2005)	August 1, 2006	Certificate
Commissioner for Patents P.O. Box 1450			AUG 0 7 2006 of Correction
Alexandria, VA 22313-1450			of Correction

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

08/03/2096 SDENBOB1 00000057 6947084

01 FC:1811

100.00 OP

Patentees' undersigned attorney may be reached in our Costa Mesa,
California office by telephone at (714) 540-8700. All correspondence should continue to
be directed to our address given below.

Respectfully submitted,

Attorney for Patentees Registration No.: 56,867

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

CA_MAIN 116472v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. :

6,947,084 B2

DATED

September 20, 2005

INVENTOR(S) :

Kaifu, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 15, "a" should read -- an --; and

Line 23, "an" should read -- a --.

COLUMN 2:

Line 5, "aspect" should read -- an aspect --.

COLUMN 3:

Line 35, "outputs" should read -- output --.

COLUMN 4:

Line 14, "a" should be deleted.

COLUMN 8:

Line 63, "frame," should read -- frame; --.

COLUMN 10:

Line 2, "and" should be deleted.

CA_MAIN 116469v1

MAILING ADDRESS OF SENDER:

PATENT NO. 6,947,084 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) (Form#30)

'AUG - 7 2006

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

: 6,947,084 B2

DATED

September 20, 2005

INVENTOR(S) :

Kaifu, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 15, "a" should read -- an --; and Line 23, "an" should read -- a --.

COLUMN 2:

Line 5, "aspect" should read -- an aspect --.

COLUMN 3:

Line 35, "outputs" should read -- output --.

COLUMN 4:

Line 14, "a" should be deleted.

COLUMN 8:

Line 63, "frame," should read -- frame; -- .

COLUMN 10:

Line 2, "and" should be deleted.

CA_MAIN 116469v1

MAILING ADDRESS OF SENDER:

PATENT NO. 6,947,084 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

1000 - 7 4**006**



Form PTO 1050 (Rev. 3-82) (Form#30)